## Drawings

1. The drawings filed on June 20, 2006 are not of sufficient quality to permit examination, in particular due to the crowding/overlap of some of the reference characters relative to the outlines of the underlying structural elements in some of the drawings (i.e., in Figures 1C, 1D, 1G, 1H, 1I, 2C) and to the unevenness of some of the lines/impermissible black shading in some of the drawings (i.e., Figures 1D, 1F, 1G, 1H, 2C, 5B, 6B, 7B, 8A, 8B). Accordingly, replacement drawing sheets in compliance with 37 CFR 1.121(d) are required in reply to this Office action. The replacement sheet(s) should be labeled "Replacement Sheet" in the page header (as per 37 CFR 1.84(c)) so as not to obstruct any portion of the drawing figures. If the changes are not accepted by the examiner, the applicant will be notified and informed of any required corrective action in the next Office action.

Applicant is given a TWO MONTH time period to submit new drawings in compliance with 37 CFR 1.81. Extensions of time may be obtained under the provisions of 37 CFR 1.136(a). Failure to timely submit replacement drawing sheets will result in ABANDONMENT of the application.

Any inquiry concerning this communication or earlier communications from the
examiner should be directed to Ljiljana (Lil) V. Ciric whose telephone number is 571-272-4909.
 The examiner works a flexible schedule, but can normally be reached weekdays between 10:30
a.m. and 6:30 p.m.

Application/Control Number: 10/583,912

Art Unit: 3744

If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Cheryl J. Tyler can be reached on 571-272-4834. The fax phone number for the organization where this application or proceeding is assigned is 571-273-8300.

Information regarding the status of an application may be obtained from the Patent Application Information Retrieval (PAIR) system. Status information for published applications may be obtained from either Private PAIR or Public PAIR. Status information for unpublished applications is available through Private PAIR only. For more information about the PAIR system, see http://pair-direct.uspto.gov. Should you have questions on access to the Private PAIR system, contact the Electronic Business Center (EBC) at 866-217-9197 (toll-free). If you would like assistance from a USPTO Customer Service Representative or access to the automated information system, call 800-786-9199 (IN USA OR CANADA) or 571-272-1000.

/Ljiljana (Lil) V. Ciric/

Primary Examiner, Art Unit 3744